# 111111 /111 mix um .... ----I-Mark Logo Programming **Technical Brochure** COLUMBIA MA

RKIA

### <u>Step 1.</u>

I-Mark

Import your desired logo into the I-Mark software. Note:

	New Workspace Open Workspace Close Workspace	10000		nikquece poulli mix	ter Shife Date 10 Test infiguration	Uninge From Workspace Flatecost	
-	Save Workspace		-	NP CS	- Active Marking	Machine	
Sava Workspace As			DKF In	purt DXF Graphie	Fleed	Ready	
	Create New Layout Open Layout Seve Layout As Export Dropot Orange User Mode	•			Trial X Abort	Home Make N Discon Come Machin	
Reat			Reat	Mindow Positions 🔥 Carlo Files	ni (b) Ent	Create	
BRE	AUN AUN AUN AUN AUN AUN AUN AUN			Preparise			

Logos must be drawn with "lines" & "arcs" only and saved in the ".dxf" format.

Select "Import DXF Graphic". In the pop up box that opens, select the appropriate .dxf file from your computer, name the logo as needed and select "open". You will

see a confirmation the drawing was converted successfully. At This time you must close out of the I-Mark software and restart it for the logo to be selectable in a layout.

## **Marking Machines**

#### <u>Step 2.</u>

Create a layout as you normally would. When needed, select the "graphic" button on the upper ribbon.



This will place a red "X" box in your

marking layout grid. Double click the box to select from the available logos.



Choose the layout and hit "Accept". This will place the logo in your layout. Note the logo can then be sized like any other entity to fit.



Note: As the logo is drawn with solid form, the default in most CMT "scribe" marking systems will attempt to "scribe" the logo during marking. For aerospace applications we will want to change the logo to the dot peen format. Follow the simple instructions below to accomplish this.

## l-Mark

<u>Step 3.</u>

With the "logo" entity highlighted in your layout, scroll to the bottom of the entity properties.



Under the "Scribing mode" heading click the box and select the "dot peen frequency" mode.

This will ensure the

marker does not scribe the logo on your part. In the same properties panel, under the "Motion" heading, highlight the "Use Global Printing Speed" and select "NO", then change the "Printing Speed" just above it to "15%".





## **Marking Machines**

#### Step 4.

Lastly, go to your machine controller header, select the machine "Properties"

tab on the left, scroll down through the properties to the "Pen" heading. Highlight the "Dot Peen On Time" setting and raise the value to "45".

Download you layout as you normally would and try out your new marking.

Shart Page / D	C150_ST - Active Mark	ing Machine	
	1	Riady	Tene an Controller 3/(21/2014 9/02 AM
Rature and Control	12214 11世		
Retire Advity	Anis 4 Length Anis 5 Length Anis 5 Length	n esne n esne	
Manual Cortrol	Aus Flengh Aus Flengh	0.0000	
Vision	Complete Output Hold Time Reverse Byte Order For EtherNet/1P)	250 No	
Disgraphics	Macellaneous IndexLocate On Time Machrist Image	10 DPS256arrg	
Contiguration	User Double 1 User Double 2	0.00000 0.000000	
Log	Unit Double 3 Unit Double 4 Unit France 1	0.00000	
Fitte	User Integer 2 User Integer	0	
Properties	Der Bing 2 User Bing 3 Der Bing 4 Der Bing 4		
	Allow Jogging Belove Harved Home 2 Times Home Before Marking	Yes No Yes	
	Home Before Marking Cycle Count Home On Bootup Velopity Blend Mode Velopity Blend Powerthom	1 Tes Dri	
	Pen Data Maria Post Res Up Time Data Maria Post Pen Diram	10	
	Dot Peen Off Taxe		
	Dot Pean On Time Time in milliseconds while pulse is active imationg)		

Note: The combination of lowering the "Printing Speed" of the logo entity and raising the "Dot Peen On Time" of the machine will increase the amount of marked "dots" in the particular



logo, these can be changed as needed until the desired appearance is achieved.